



FIG. 1



2 / 9

FIG. 2



3 / 9


# FIG. 3


DRAWING ATTRIBUTE REGISTER

201

0	AUTOMATIC SWITCHING MODE ENABLE D0
1	AUTOMATIC SWITCHING MODE ENABLE D1
2	AUTOMATIC SWITCHING MODE ENABLE D2
3	AUTOMATIC SWITCHING MODE ENABLE D3
4	AUTOMATIC SWITCHING MODE ENABLE D4
5	AUTOMATIC SWITCHING MODE ENABLE D5
6	AUTOMATIC SWITCHING MODE ENABLE D6
7	AUTOMATIC SWITCHING MODE ENABLE D7
8	
26	
27	
28	
29	
30	
31	


FIG. 4





6 / 9

FIG. 6




7 / 9

FIG. 7

DISPLAY ADDRESS OF  
DISPLAY PLANE 0

VSYNC#

DISPLAY ADDRESS OF  
DISPLAY PLANE 0DISPLAY ADDRESS OF  
DISPLAY PLANE 1ADR00 OF DISPLAY PLANE 0  
IS DISPLAYEDDISPLAY ADDRESS OF  
DISPLAY PLANE 1


ADR01 OF DISPLAY PLANE 0 IS DISPLAYED

ADR11 OF DISPLAY PLANE 1 IS DISPLAYED

DRAWING DESTINATION  
ADDRESSADR10 OF DISPLAY PLANE 1  
IS DISPLAYEDDRAWING IS  
PERFORMED IN  
ADR10 OF DISPLAY  
PLANE 1DRAWING IS  
PERFORMED IN  
ADR00 OF DISPLAY  
PLANE 0DRAWING  
STARTTRAP COMMAND  
FETCH  
(D0~D7=0)DRAWING  
STARTTRAP COMMAND FETCH  
(D0=1, D1=1, D2~D7=0)

8 / 9

FIG. 8



9/9

